

Written Quiz

POINTS

1. What are three basic operations that can be accomplished with a McLeod? 15
 - a. _____
 - b. _____
 - c. _____

2. Why do you not paint the head of a McLeod? 10

3. The cutting edge is sharpened at a _____ angle. 5

4. When do you apply linseed oil to a McLeod handle? 10

5. When should a McLeod be inspected? 10

6. How should you carry a McLeod? 15

7. When using a McLeod, what is the minimum working distance? 10

8. List three (3) characteristics of a serviceable McLeod handle. 15
 - a. _____
 - b. _____
 - c. _____

Written Quiz

MCLEOD

POINTS

9. When carrying a McLeod and passing another person, you should do what?

10

POINTS POSSIBLE: 100

POINTS DEDUCTED:

FINAL SCORE:

Written Quiz - Key

MCLEOD

	<u>POINTS</u>
1. What are three basic operations that can be accomplished with a McLeod? a. SCRAPING b. CUTTING c. RAKING DIGGING GRUBBING	<u>15</u>
2. Why do you not paint the head of a McLeod? WILL HIDE DEFECTS AND CRACKS IN HEAD	<u>10</u>
3. The cutting edge is sharpened at a 45° angle.	<u>5</u>
4. When do you apply linseed oil to a McLeod handle? NEVER	<u>10</u>
5. When should a McLeod be inspected? BEFORE AND AFTER EACH USE	<u>10</u>
6. How should you carry a McLeod? ON DOWNHILL SIDE AT BALANCE POINT WITH TINES TOWARD BODY MCLEOD PARALLEL TO EARTH'S SURFACE FLAT BLUNT EDGE UP	<u>15</u>
7. When using a McLeod, what is the minimum working distance? 10'	<u>10</u>
8. List three (3) characteristics of a serviceable McLeod handle. a. SMOOTH b. STRAIGHT c. STURDY	<u>15</u>

4315.6

Page 1

POINTS

9. When carrying a McLeod and passing another person, you should do what?

10

ANNOUNCE "COMING THROUGH" PRIOR TO PASSING

POINTS POSSIBLE: 100

POINTS DEDUCTED:

FINAL SCORE: